



INPECT BC

| | |
|--|--------|
| | |
| | 350mm |
| | 160 mm |
| | 160 mm |
| | 1 |
| | 400 |
| | |


1-

| | | |
|--------------------------|---------------------------|---------|
| | | |
| | stuck glass | >0.6 mm |
| Sidewall area inspection | blemish | |
| | blister | |
| | strong mold seam or wings | |
| | dirt | |
| | black particle | |
| | stone | |
| | visible crack | |
| | strong uneven glass | |
| | | |




2-

| | | |
|--|-------------------------------|--|
| | | |
| | defect below sealing | |
| | defect in jar screw | |
| | defect in jar sealing surface | |



3-

| | | |
|---------------------------------|--------------------------|--|
| | | |
| | strong uneven glass | |
| Low contrast sidewall detection | laps | |
| | wrinkles | |
| | glass | |
| | skin blisters | |
| | visible horizontal crack | |




4-

| | | |
|--|----------------|--------|
| | | |
| | stressed stone | >0.5mm |
| | Unmelt glass | >0.5mm |
| | stress defect | >0.5mm |

5-

| | | |
|--|-------|------|
| | | |
| | 160mm | >1mm |
| | 350mm | |
| | | |



6-

| | | |
|--|---------------------------------|--------|
| | | |
| | stone | >0.6mm |
| | impurity | |
| | stuck glass | |
| | bubbles | |
| | dirty spot | |
| | checks | |
| | defect in stiplings & engraving | |
| | wrinkles | |

7-

| | | |
|--|--------------------------|--------|
| | | |
| | stone with stress | >0.5mm |
| | impurity with stress | |
| | Unmelt glass with stress | |
| | stress defect | |
| | bad annealing stress | |

| | | |
|--|--|--|
| | | |
|--|--|--|

8-

| | | |
|--|-----------------|--------|
| | | |
| | finish blisters | |
| | / Overpress | |
| | line over | >0.1mm |
| | | |
| | wire edge | >0.1mm |
| | | |
| | | |

9-

| | | |
|--|--|-----|
| | | |
| | | 99% |
| | | 99% |



577

0533- 6166158

www.sanjinglass.com